
#62-137-00 REV (0)

LIGHTWAY INDUSTRIES

INSTALLATION INSTRUCTIONS



- For proper installation, have a qualified electrician install this product.
- 2. Expose the supply wiring from the outlet box.
- . Run the supply wiring out of the outlet box.
- screws (provided by others). Attach the canopy mounting bracket to the outlet box using mounting
- $\dot{\Omega}$ the chassis. Then secure the tube onto the coupling by using the setscrew chassis assembly to the tube by threading the tube into the coupling on Feed the wires from the light fixture through the tube then attach the
- .7 groove in the half ball with the bracket tabs and rotate the ball in. the half ball can be pushed in the mounting bracket by lining up the Attach the tube to the canopy bracket by rotating the assembly so that
- $\dot{\infty}$ Make sure that the half ball is secure in the canopy mounting bracket and bracket cavity so that the half ball can swing slightly but not rotate line up the groove in the half ball with the alignment tab in the mounting
- 9. Connect the wires:
- Connect the grounding wire (green or bare copper) from the supply circuit to the green wire(s) from the fixture
- 9.2. Connect the white wire from the fixture to the white wire(s) of the supply circuit.
- supply circuit. Connect the black wire from the fixture to the black wire(s) of the
- 10. Secure the canopy to the mounting bracket by lining up the tabs on the bracket and rotate the canopy until secure.
- 11. Install the lamps. Do not exceed recommended wattage.
- 12. Install the cover with lens using the eight screws (included).
- 13. Restore power.